Wm. Sellers, President. Ichn Sellers Ir Vice Frest, V Treas. Iustius H. Schwacke, Secretary. J. Sellers Bancroft; Managen Coloman Sellers, Engineer. D. Lukons, Perchasing Agent. William Letters & Co., Incorporated.

Philadelphia Sept. 26, 1887

Messrs. Wilson, Bros. & Co.

435 Ches tnut St., Phila.

Gentlemen:

We have your favor of the 23rd inst. regarding the Shafting at the Mint, with special reference to the slipping of the belt driving the Coining Room. We sent a Miliwright today to treat belt dressing and he reports to us that under that treatment the slipping was nearly if not entirely checked. It is our impression that these belts have not been used under the most favorable conditions, as new belts should be subjested to frequent and judicious treatment to render them pliable and adhesive. The slipping complained of is mostly in the 18" belt running from the line on floor of East Passageway to line shafting under the Coining Room. The work which we erected there seems to be all right as far as it goes but it may be possible that at this particular point it would be well to go farther. We would therefore recommend, 1st., that they have the 42" Receiving Pulley on the main line covered with leather and all the belts well dressed with some good quality of belt dressing. If this W. B. &Co. , 2.

gest that they have a belt tightener erected so as to regulate
the tension on the belt above referred to. We think that the success of this arrangement depends largely upon the quality of the
belting and its capacity to transmit power without stretching.

Yours truly

Wm. Sellers & Co. Incorporated,

to Short

Secretary.

un der all

William Sellers & Co., Incorporated. Philadelphia, September 26, 1887

Messrs. Wilson, Bros. & Co. 435 Chestnut St., Phila.

Gentlemen:

We have your favor of the 23rd inst. regarding the Shafting at the Mint, with special reference to the slipping of the belt driving the Coining Room. We sent a Millwright today to treat this belt with a belt dressing and he reports to us that under that treatment the slipping was nearly if not entirely checked. It is our impression that these belts have not been used under the most favorable conditions, as new belts should be subjected to frequent and judicious treatment to render them pliable and adhesive. The slipping complained of is mostly in the 18" belt running from the line on floor of East Passageway to line shafting under the Coining Room. The work which we erected there seems to be all right as far as it goes but it may be possible that at this particular point it would be well to go farther. We would therefore recommend, 1st, that they have the 42" Receiving Pulley on the main line covered with leather and all the belts well dressed with some good quality of belt dressing. If this does not entirely overcome the difficulty we would further suggest that they have a belt tightener erected so as to regulate the tension on the belt above referred to. We think that the success of this arrangement depends largely upon the quality of the belting and its capacity to transmit power without stretching.

Yours truly Wm. Sellers & Co. Incorporated, Justus H. Schwacks Secretary.